

FTS389 - FORD TRITON SPARK PLUG REPAIR

**Ford Triton Spark Plug Thread Repair Kit
Part No. 38900
Replacement Parts**



Item: FTS389

Description: FORD TRITON SPARK PLUG REPAIR

Notes: N/A

Figure No	Part Number	Description	No. Reqd	Warranty Code
1	K8393-300	TAP 3 VALVE KIT F/FT393	1	K
2	K8389-200	11/16 CORE DRILL F/FTS389	1	K
3	K8389-400	GUIDE F/FTS389	1	K
4	*K8MSI610A	DVD, INSTRUCTIONAL	1	
5	K8389-900	BLOW MOLDED CASE F/FTS389	1	X
6	K8389-100	INSERT F/38900	8	K
7	K8390-400	SBR TUBING F/ FTS389	1	X
8	K8370-700	NEEDLE VALVE FOR FTS389	1	X
9	K8560-16	1/8 POLY BARB CONNECTOR-FTS389	1	X
10	K8390-200	STOPPER F/ FTS389	1	X
11	*K8390-300	PLUG 1/8" NPTF MALE THREAD	1	