


## L8335FZ - FLEXILLA 1/2 IN. X 50 FT.



Repair Parts		
Ref. #	Repair Part	Description
1	L8300-W	Bracket for wall or overhead ceiling mounting
2	RP065002BK	Outer Top Case w/Tin Ring Stack
3	RP065002BK	Swivel Plate Side Assembly Black
4	RP065007-38	Swivel Body Assembly 3/8 in. hose
4	RP065007-12	Swivel Body Assembly 1/2 in. hose
4	RP065007-58	Swivel Body Assembly 5/8 in. hose
5	RP065015	Drum Assembly for 50 ft. hose
5	RP065015	Drum Assembly for 75 ft. & 100 ft. hose
6	RP065010-14	Layering Device Assembly for Model L8335, L8335-EU, L8344, L8346, L8347 & L8349
6	RP065010-20	Layering Device Assembly for Model L8305, L8305N, L8305-EU, L8306, L8306-EU, L8310, L8310-EU, L8345, L8346 & L8350-EU
7	RP065012-137	Drive Bell for Model L8335, L8335-EU, L8344, L8346, L8347 & L8349
7	RP065012-140	Drive Bell for Model L8305, L8305N, L8305-EU, L8306, L8306-EU, L8310, L8310-EU, L8345, L8350 & L8350-EU
8	RP065004BK	Latch Plate Side Assembly Black
9	RP065003	Tension Cover
10	RP065001BK	Outer Bottom Case Black
11	RP065018	Latch Spring and Pin
12		Lead-in Hose ( See Replacement Lead-in Hose table on Page 4 )
13	RP065026	Hose Stopper for 3/8 in. hose - L8305, L8306, L8310
13	RP065027	Hose Stopper for 1/2 in. hose - L8305, L8345, L8350
13	RP065028	Hose Stopper for 5/8 in. hose and Dry/Wet, Dry/Fuel L8344, L8346, L8347, L8349, L8363, L8366
14		Hose ( See Replacement Hose Kit table on Page 2 )

Lead-in Hose Replacement	
Part #	Description
L8305LI	3 ft. lead-in hose for L8305, L8306 & L8310
L8305LI-10	10 ft. lead-in hose for L8305, L8306 & L8310
L8305LI-EU	3 ft. lead-in hose for L8305-EU, L8306-EU & L8310-EU
L8305LI-10-EU	10 ft. lead-in hose for L8305-EU, L8306-EU & L8310-EU
L8305NLI	3 ft. lead-in hose for L8305N
L8335LI	3 ft. lead-in hose for L8335
L8335LI-10	10 ft. lead-in hose for L8335
L8335LI-EU	3 ft. lead-in hose for L8335-EU
L8335LI-10-EU	10 ft. lead-in hose for L8335-EU
L8345LI-10	10 ft. lead-in hose for L8345
L8347LI	3 ft. lead-in hose for L8347
L8347LI-10	10 ft. lead-in hose for L8347
L8349LI	3 ft. lead-in hose for L8349, L8344 & L8346
L8349LI-10	10 ft. lead-in hose for L8349
L8350LI-10	10 ft. lead-in hose for L8350
L8350LI-10-EU	10 ft. lead-in hose for L8350-EU

### TWO YEAR LIMITED WARRANTY\*

LEGACY MANUFACTURING COMPANY ("LEGACY") warrants that this equipment will be free from defects in material and workmanship for a period of two (2) year from the date of purchase, under normal use. LEGACY'S sole obligation under this warranty is limited to replacing or repairing, free of charge, any equipment that proves to be defective under normal conditions and use according to the recommendations of LEGACY. To obtain repair or replacement, the equipment must be shipped to a LEGACY authorized Warranty and Service Center during the warranty period. Transportation charges prepaid, with proof of date of purchase. In the event of repair or replacement, the warranty period shall not be extended beyond the original warranty period.

\* If this equipment contains a hose, the hose is warranted for ninety (90) days only. The remaining portions of this equipment are warranted for two (2) year, as described above. While necessary maintenance or repairs on your Legacy equipment can be performed by any company, we recommend that you use only authorized Legacy service centers. Improper or incorrectly performed maintenance or repair voids this warranty. Contact us at info@legacymfg.com or www.legacymfg.com for ordering, installation instructions, or a list of authorized service centers.

**WARNING:** This product contains one or more chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. **Wash hands after handling.**



Legacy Manufacturing Company  
 6281 North Gateway Drive • Marion, IA 52302 USA  
 Tel (319) 373-7305 • Fax (319) 373-7309  
 info@legacymfg.com • www.legacymfg.com

Item: L8335FZ

Description: FLEXILLA 1/2 IN. X 50 FT.

Notes: N/A

Figure No	Part Number	Description	No. Reqd	Warranty Code
-----------	-------------	-------------	----------	---------------