

AC71202 - NEW HYDRAULIC YOKE F/ AC72475A



Item: AC71202

Description: NEW HYDRAULIC YOKE F/ AC72475A

Notes: The AC71202 has been changed from a D warranty to an M warranty. to promote replacement of parts rather than the entire tool. The replacement items and repair kits in the Bill of Material should be investigated for replacement before sending in the entire tool for replacement. Should the entire tool need send for replacement you must first contact the Supplier to discuss what the issue is with the tool. If the repair kit and replacement parts cannot correct the problem the supplier should replace the tool. Supplier can be contacted at phone number: (973) 252-9119. TOLL FREE: 1-888-825-6989 EMAIL: techs@mastercool.com

Figure No	Part Number	Description	No. Reqd	Warranty Code
1	NJ71201001AR	REPAIR KIT F/AC71475	1	X
2	*NJ71202-001B-NEW	NEW YOKE ASSEMBLY CONSISTS OF FIG. C, U, V, W, B, A	1	
3	*NJ71202-18K-NEW	COMPLETE NEW YOKE & FRONT SHAFT ASSEMBLY CONSISTS OF FOG. E, K, J, G, A, I, C	1	
4	NJ71201REKIT	PISTON SHAFT REPAIR KIT F/7120	1	X