


MD75300 - SECONDARY IGNITION PICKUP



Item: MD75300

Description: SECONDARY IGNITION PICKUP

Notes: N/A

Figure No	Part Number	Description	No. Reqd	Warranty Code
1	R116970-196	SIGNAL RECEIVER PAD	1	х
2	R116970-201	SIGNAL RECIVER PAD	1	D