

TSB100F72 - 72 3/8 DRIVE SPLIT BEAM 100F



Item: TSB100F72

Description: 72 3/8 DRIVE SPLIT BEAM 100F

Notes: N/A

Figure No	Part Number	Description	No. Reqd	Warranty Code
1	*H1TSB100F72RK	3/8" 72 TOOTH REPAIR HEAD KIT	1	
2	*H1TSB100F-UH	UPPER HANDLE HALF	1	
3	*H1TSB100F-LH	LOWER HANDLE HALF	1	