


7077 - AXLE STUD CONE PLIER



Item: 7077

Description: AXLE STUD CONE PLIER

Notes: N/A

Figure No	Part Number	Description	No. Reqd	Warranty Code
1	*FU10009	CAP SCREW	1	
2	*FU13639	LOCK NUT	1	
3	*FU42808	PLIER HALF	1	
4	*FU37487	PLIER HALF	1	